

FIG. 1




FIG. 2




FIG. 3




FIG. 4

4/15




FIG. 5




FIG. 6





FIG. 7



**FIG. 8**

8/15

PEN OPERATION MODE		PEN POINT SW41	SW1 42a	SW2 42b	Z-DIRECTION	X- AND Y- DIRECTIONS	ABSOLUTE COORDINATE	OUTPUT COORDINATE VALUE
PEN UP	PEN DOWN							RELATIVE COORDINATE
PEN INPUT	○	OFF	OFF	OFF		= 0	INSIDE AREA	○
	○	ON	—	—		= 0	OUTSIDE AREA	NG
	○	ON	—	—		≠ 0	—	NG
PROXIMITY INPUT	○	OFF	ON	OFF	PREDETERMINED VALUE 1 OR LESS	INSIDE AREA	○	NG
	○	OFF	OFF	ON	PREDETERMINED VALUE 1 OR LESS	OUTSIDE AREA	○	NG
	○	OFF	ON	ON	PREDETERMINED VALUE 1 OR LESS	OUTSIDE AREA	○	NG
REMOTE INPUT	○	OFF	ON	ON	PREDETERMINED VALUE 1 OR LESS	INSIDE AREA	○	—
	○	OFF	ON	OFF	PREDETERMINED VALUE 1 OR MORE	OUTSIDE AREA	○	—
	○	OFF	ON	ON	PREDETERMINED VALUE 1 OR MORE	—	○	—

FIG. 9




FIG. 10




FIG. 11





FIG. 12



**FIG. 13**





FIG. 14



## FIG. 15

